


CENTURY MINE MITIGATION STREAM MITIGATION PHOTOGRAPHS
Long Run



Photograph: 80
LRR-10: Eroded bank in area of coir log installation



Photograph: 81
LLR-12: Eroded bank in area of coir log installation



Photograph: 82
LRR-14: Partially successful log vane, J-hook complex



Photograph: 83
LRR-15: Eroding stream bank